Hybrid III 95th Large Male Left Shoulder Assy

VESTA





9000043
Screw, SHSS 1/2 x 1

9008007
Washer, Flat
.515 ID x .875 OD

880995-339
Spacer, Clavicle

880995-338
Clavicle Spring Stop

880995-334
Clavicle Link ,
Left

78051-238
Nut, Clavicular
Link Pivoting

78051-237
Washer, Nut,
Clavicular Link
Pivoting

78051-236
Washer, Clavicular
Link Pivoting

9006001
Screw, SHSS 1/2 x 1 1/4

880995-358
Bushing

9001015
Nut, Hex Jam
3/8-16 w/Nylok

78051-190
Bushing

880995-336
Clavicle Assembly,
Left, HIII 95th

880995-346
Stop Steel
Shoulder Pivot

880995-349
Shoulder Yoke
Pivot Washer

880995-347
Shoulder Pivot
Stop

9000047
Screw, SHCS 10-24 x 3/8

9000041
Screw, SHCS
1/4-20 x 3/8

78051-245
Stop Assembly,
Shoulder

880995-343
Shoulder Yoke
Assembly

880995-348
Bushing, Shoulder
Yoke Pivot

78051-248
Washer—Shoulder
Yoke Pivot

78051-249
Washer—Shoulder
& Elbow Joint Spring

78051-250
Washer—Shoulder
Yoke Retaining

ROBERT A. DENTON, INC. Tel 248-852-5100 • email: info@radenton.com • www.radenton.com
DENTON ATD, INC. Tel 419-625-5200 • email: info@dentonatd.com • www.dentonatd.com
DENTON COE GMBH Tel +49 6221 33 50 80 • email: info@dentoncoe.de • www.dentoncoe.de

Release Ver. 1.0

© Mar. 1, 2004