Hybrid III 50th Male
Left Shoulder Assembly

VESTA



78051-360
Yoke Assembly—
Shoulder

78051-245
Stop Assembly—
Shoulder

9006001
Screw,
SHSS 1/2 x 1 1/4

9000043
Screw, SHSS 1/2 x 1

78051-243
Flat Washer

9001015
Nut, Hex Jam
3/8-16 w/Nylok

78051-243
Flat Washer

78051-200
Washer—Upper
Arm, elbow Pivot

78051-241
Spacer—Clavicle

9000047
Screw, SHCS 10-24 x 3/8

78051-199
Bushing—Upper
Arm, elbow Pivot

78051-240
Spring—Clavicle
Stop (Fore & Aft)

78051-244
Stop, Steel,
Shoulder Yoke Pivot

78051-249
Washer—Shoulder
& Elbow Joint
Spring

78051-238
Nut, Clavicular
Link Pivoting

78051-188
Clavicle Link
Assembly, LH

78051-202
Upper Arm
Pivot Nut

78051-237
Washer, Nut,
Clavicular
Link Pivoting

78051-246
Bushing, Shoulder
Yoke Pivot

78051-247
Washer, Shoulder
Yoke Pivot

78051-236
Washer, Clavicular
Link Pivoting

78051-155
Clavicle
Bushing

9000041
SHCS
1/4-20 x 3/8

78051-250
Washer—
Shoulder
Yoke
Retaining

78051-249
Washer—Shoulder
& Elbow Joint
Spring

78051-248
Washer—Shoulder
Yoke Pivot

9006001
Screw, SHSS
1/2 x 1 1/4

78051-190
Bushing, Clav
Pivot

78051-141
Clavicle
Assembly,
Left, HIII 50th

78051-242
Stop Assembly—
Rubber, Shoulder
Yoke Pivot

ROBERT A. DENTON, INC. Tel 248-852-5100 • email: info@radenton.com • www.radenton.com
DENTON ATD, INC. Tel 419-625-5200 • email: info@dentonatd.com • www.dentonatd.com
DENTON COE GMBH Tel +49 6221 33 50 80 • email: info@dentoncoe.de • www.dentoncoe.de

Release Ver. 1.0
© Mar. 1, 2004